P-9 SSR - 240V RELAY

Factory wiring reference - verify exact kiln configuration before service.

GROUND CONNECTION: The equipment grounding conductor is shown at the power-cord entry at the lower left. Confirm the grounding connection against the factory wiring diagram before servicing.

AIM MANUFACTURING & KILN COMPANY

